

SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

DESCRIPTION

SK2TM180-2 is an advanced epoxy matrix system designed for composite tooling construction.

SK2TM180-2 supplied in the form of carbon* prepreg to offer the following advantages:

- low temperature cure: 14 hours at 45°C
- excellent surface finish
- work life of 2-3 days at room temperature (23°C) and 6 months when stored at -18°C
- low shrinkage during the curing and post-curing process
- service temperature over 180°C after post-cure
- solvent free formulation

* SK2TM180-2 can also be supplied in the form of glass prepreg on special order

The 3 different types of prepreg SK2TM180-2 are available:

Reference	Areal weight	Resin content
SK2TM180-2PRE50	204 g/m ₂	50%
SK2TM180-2PRE35	630 g/m ₂	35%
SK2TM180-2PRE34	995 g/m2	34%

► TECHNICAL CHARACTERISTICS

SK2TM180-2PRE50				
Dry fabric	Unit			
Weaving Style	TWILL 2/2 BATAVIA 2/2	-		
Fiber type	T300 3K or equivalent	-		
Fiber density	1.76	g/cm₃		
Warp	5.1	threads/cm		
Weft	5.1	threads/cm		
Areal weight	204 (± 4%)	g/m2		

VIK-COMPOSITE

SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

Uncured prepreg	Typical values	Unit
Tack	Medium-High	-
Flow	21 (± 5%)	%
Out life at 23°C	3	days
Storage life at -18°C	6	months
Nominal Area weight	408	g/m2
Nominal Resin content	50 (± 3)	Wt %
Volatile content	< 1	Wt %
Nominal width	1000	mm
Cured Ply Thickness*	0.282	mm

* The tests were carried out at 23°C and 60% R.H. on specimens cured in std conditions (dwell at 45°C for 14 hours in autoclave. External pressure applied: 6 bar).

SK2TM180-2PRE35				
Dry fabric	Unit			
Weaving Style	TWILL 2/2 BATAVIA 2/2	-		
Fiber type	T700 12K or equivalent	-		
Fiber density	1.8	g/cm₃		
Warp	3.9	threads/cm		
Weft	3.9	threads/cm		
Areal weight	630 (± 4%)	g/m ₂		
Uncured prepreg	Uncured prepreg Typical values			
Tack	High	-		
Flow	13 (± 5%)	%		



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

Out life at 23°C	3	days
Storage life at -18°C	6	months
Nominal Area weight	969	g/m2
Nominal Resin content	35 (± 3)	Wt %
Volatile content	< 1	Wt %
Nominal width	1270	mm
Cured Ply Thickness*	0.626	mm

* The tests were carried out at 23°C and 60% R.H. on specimens cured in std conditions (dwell at 45°C for 14 hours in autoclave. External pressure applied: 6 bar).

SK2TM180-2PRE34					
Dry fabric Typical values Unit					
Weaving Style	TWILL 2/2 BATAVIA 2/2	-			
Fiber type	AKSA 24K	-			
Fiber density	1.78	g/cm₃			
Warp	3.0	threads/cm			
Weft	3.0	threads/cm			
Areal weight	995 (± 4%)	g/m2			
Uncured prepreg	Typical values	Unit			
Tack	High	-			
Out life at 23°C	3	days			
Storage life at -18°C	6	months			
Nominal Area weight	1508	g/m2			
Nominal Resin content	34 (± 3)	Wt %			
Volatile content	< 1	Wt %			

It remains responsibility of the user to verify that this product meet the requirement of the process applied.



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

Nominal width	1270	mm
Cured Ply Thickness*	0.976	mm

* The tests were carried out at 23°C and 60% R.H. on specimens cured in std conditions (dwell at 45°C for 14 hours in autoclave. External pressure applied: 6 bar).

PROCESSING INFORMATION

MASTER MODEL SELECTION

Master model material should be selected with reference to the temperature and pressure to be applied during the autoclave cure process. In all cases the master model must be proved at the temperature and pressure above that of the desired cure cycle before beginning lay-up of the tool. This will enable any potential problems such as lack of vacuum integrity or poor stability under pressure to be checked before any actual laminate construction. The master model must be constructed from materials that will not cause adverse reactions with the tooling prepreg resin system. Equally, it should not be coated with a sealer that will allow migration of chemicals which cause problems.

MASTER MODEL PREPARATION PROCEDURE

- Thoroughly degrease the master model surface using an organic solvent
- Seal the surface of master model with a suitable epoxy surfacing resin using wipe on buff off technique
- Thoroughly degrease the master model surface ensuring all solvent is removed
- Apply a semi-permanent, solvent-based release agent from our SK2TR range such as SK2TR450-12 to the surface following the instructions
- Allow the final coat to cure for 15 to 20 minutes at 22°C

THAWING PREPREG BEFORE USE

SK2TM180-2 prepregs must be stored at -18°C, sealed in original packages. Shop life at 23°C refers to rolls sealed in original packages. Before using the prepreg, remove the roll from the freezer and let it warm up to room temperature for 6 hours sealed in its original package. Prepreg rolls are considered sufficiently warm when condensation no longer forms on the outside of the bag. Ensure there is adequate material available to complete laminating and cure, prior to unsealing the roll and starting work.

OPERATIONAL INSTRUCTIONS

- Always wear nitrile gloves when handling prepreg;
- Cut the prepreg into convenient sized squares or rectangles for laminating;



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

- Cut 45° trim strips for the external corners and tight radii;
- Cleanliness is very important during the lay-up procedure. Avoid introducing any contaminates into the lay-up, i.e. paper, polythene or release film, as these will adversely affect the tool laminate and may lead to premature tool failure;
- Table 1 shows a copy of a typical work sheet with easy reference for ply type and fibre orientation.
- Lay up the first ply, carefully cutting and keep in mind the following points:
 - 1. All pieces should be overlapped of 3,0 mm (1/8 inch)
 - 2. Lay up a series of 45° trim strips in to all external corners and tight radii, ensure pattern runs in a consistent direction for aesthetics;
 - 3. Cut material to fit into all external radii and corners taking care not to disturb the trim strips.
 - 4. To avoid bridging, no single piece of prepreg should ever be laid up around more than one corner;
 - 5. Ensure that Prepreg is spliced in corners and any female tight radii in order to avoid wrinkling.
- Lay up the bulk plies following these instructions:
 - 1. Butt jointing is preferable on subsequent plies but care must be taken so that the joints on each ply are staggered with a minimum of 18 mm (3/4 inch) spacing for adjacent plies;
 - 2. If overlapping is unavoidable on subsequent plies ensure the overlap is a maximum of 3.0 mm (1/8 inch) wide and that overlaps are staggered;
 - 3. Under no circumstances should any gaps be left as this is likely to cause voids in the completed tool.

DEBULKING

It is essential to debulk the prepreg at least at the stages stated in table 1. This will ensure even consolidation and remove air from the laminate prior to final curing. More complex shapes can sometimes be easier to laminate if more frequent debulks are used, but in these cases, the time factor must be taken into consideration.

Debulk the lay-up per the following steps:

- 1. Cover the lay-up with a suitable (PC type) perforated release film (e.g. SK2RF230-1 or SK2230-2 with perforation PC) ensuring no bridging and extending beyond the layup by approximately 25mm (1 inch);
- 2. Apply peel ply from the rang of SK2PP over the release film.
- 3. Apply a breather fabric SK2BB205-4 over the peel ply. Tailor to fit avoid bridging. Do not use a non-woven polyester breather without a peel ply is first applied over the release film. Filaments from the polyester breather left in the laminate may cause premature tool failure.

It remains responsibility of the user to verify that this product meet the requirement of the process applied.



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

- 4. Cover the laminate/assembly with a vacuum bag and apply full vacuum of 948 mbar (28 inches Hg) for a minimum of 30 minutes.
- 5. Care must be taken when materials are removed from the surface afterwards, be careful not to lift up the previously laminated plies.

TYPICAL LAY-UP SEQUENCE AND OPERATION FOR A CARBON FIBER REINFORCED LAMINATE OF TOTAL THICKNESS 5.60 mm

Operation N	Ply orientation	Material / Operation
1	0°	SK2TM180-2PRE50
2		DEBULK
3	0°	SK2TM180-2PRE35
4	+45°	SK2TM180-2PRE35
5		DEBULK
6	-45°	SK2TM180-2PRE35
7	90°	SK2TM180-2PRE35
8	90°	SK2TM180-2PRE35
9		DEBULK
10	-45°	SK2TM180-2PRE35
11	+45°	SK2TM180-2PRE35
12	0°	SK2TM180-2PRE35
13		DEBULK
14	0°	SK2TM180-2PRE50

The initial choice of the direction which will be 0° is arbitrary, but, once chosen, subsequent angles must be measured relative to this direction.

SK2TM180-2PRE50 is a 204 g/m₂, 2x2 twill, 3K carbon fabric with 50% resin content SK2TM180-2PRE35 is a 630 g/m₂, 2x2 twill, 12K carbon fabric with 35% resin content



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

REDUCED LAY-UP SEQUENCE AND OPERATION FOR A CARBON FIBER REINFORCED LAMINATE OF TOTAL THICKNESS 6.40 mm

Operation N	Ply orientation	Material / Operation
1	0°	SK2TM180-2PRE50
2		DEBULK
3	0°	SK2TM180-2PRE34
4	45°	SK2TM180-2PRE34
5		DEBULK
6	90°	SK2TM180-2PRE34
7	90°	SK2TM180-2PRE34
8		DEBULK
9	45°	SK2TM180-2PRE34
10	0°	SK2TM180-2PRE34
11		DEBULK
12	0°	SK2TM180-2PRE50

The initial choice of the direction which will be 0° is arbitrary, but, once chosen, subsequent angles must be measured relative to this direction.

SK2TM180-2PRE50 is a 204 g/m₂, 2x2 twill, 3k carbon fabric with 50% resin content SK2TM180-2PRE34 is a 995 g/m₂, 2x2 twill, 24k carbon fabric with 34% resin content

► OPERATIONAL INSTRUCTIONS

This epoxy matrix system can be processed at low temperature, starting from 23°C.

Temperature °C	Time	Tg °C DSC
45 °C	14 h	69 °C
55 °C	7 h	75 °C



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

CURE PROCESS RECOMMENDATIONS

The curing cycles recommended are:

1. 14h at 45°C, ramp 0,5°C/min:

- Dwell at RT for 60 minutes under full vacuum
- Apply a pressure of 6 bar
- Heat the laminate at a rate of 0.5°C/min to 45°C
- Hold the laminate at 45°C for 14 hours
- Cool the laminate to RT under pressure at 2°C/min

The Tg of the laminate made using this cure cycle is 63°C (by DMA onset).

2. 7h at 55°C, ramp 0,5°C/min:

- Dwell at RT for 60 minutes under full vacuum
- Apply a pressure of 6 bar
- Heat the laminate at a rate of 0.5°C/min to 55°C
- Hold the laminate at 55°C for 7 hours
- Cool the laminate to RT under pressure at 2°C/min

The Tg of the laminate made using this cure cycle is 72°C (by DMA onset).

► POST-CURE

An unsupported post cure can be applied to reach the necessary service temperature of the carbon tool. All the cycle below are performed with a 0,2°C/min heating ramp:

Cure	Postcure	Tg °C E' DMA	Tg °C tan & DMA	% cure by DSC
14h at 45°C	5h at 180°C	189°C	222°C	100%
7h at 55°C	5h at 180°C	191°C	228°C	100%

BAGGING & LAY-UP RECOMMENDATIONS

- 1. The tool master should be sealed and coated with release agent.
- 2. When the prepreg is laid up on the mold, splices should be staggered.
- 3. Small strips of prepreg can be placed in tight corners and radii to insure that there is no bridging of the Prepreg.



- 4. A thermocouple should be placed under the second ply, in an area that is not critical to the aesthetics of the part.
- 5. A Non Perforated release film is placed on the top of the last layer of prepreg.
- 6. Pin prick the solid release film every 100-150mm across the surface of the tool. This is to form vacuum connections to the breather.
- 7. Breather cloth, minimum 300 gsm weight, is applied of the entire part, with a double layer where the vacuum ports are attached.
- 8. The vacuum bag is placed over the part with sufficient slack to avoid bridging in corners.
- 9. Perform a vacuum check to insure there are no leaks and that > 914 mbar vacuum (27 in Hg) is achieved.

Property	Value	Unit	Standard
Storage life at -18°C	6	months	
Work life at 23°C	2-3	days	
Cured resin density	1.23	g/cm ₃	ASTM D792-00
Tg E' (DMA)*	191	°C	ASTM E1640-09
Tg Peak Tan δ (DMA)*	228	°C	ASTM E1640-09
CTE*	4-6 x 10 -6	°C-1	ISO 11359-2
Tack	High		

GENERAL PROPERTIES OF THE RESIN MATRIX

* Laminate fully cured 7h at 55°C plus post cure 5h at 180°C

► THERMO-MECHANICAL DMA ANALYSIS

DMA trace of the prepreg SK2TM180-2 laminate cured for 7h at 55° C + post cure 5h at 180°C.



Modulus E' evaluated under 2°C/min heating rate, 1Hz oscillating frequency.



VISCOSITY PROFILE

Resin complex viscosity' evaluated under 3°C/min heating rate, 1Hz oscillating frequency.



GEL TIME



Temperature °C	Gel time (min)
45°C	653 min
55°C	325 min
70°C	85 min

► SAFETY CONSIDERATION

- Please consult the Material Safety Data Sheet.
- This product contains epoxy resin, and may cause allergic reaction.
- The use of latex gloves for handling is recommended.
- Waste material should be discarded following national law.

► DELIVERY FORM AND PACKAGING

Custom widths, roll size, and packaging are available on request.



SK2TM180-2

Prepreg with epoxy matrix and carbon reinforcement for composite tooling

Prepreg fabrics: Supplied on 75 mm (3") diameter cardboard cores with release paper on one side and polyethylene film separator on the other side. Rolls are sealed plastic bags and packed in cardboard boxes.
Standard width: 100 cm (39.4") or 127 cm (50").
Standard length: 50 m (54.7 in yds).

Unidirectional Prepreg: Supplied on 300 mm (12") diameter cardboard cores with release paper on one side and smooth polyethylene film separator on the other side. Rolls are sealed in plastic bags and packed in cardboard boxes. **Standard width:** 60cm (23.6"), range from 30cm (11.8") up to 105cm (41.3") **Standard length:** 100 m (109 in yds).

Shipment: Product should be shipped at < -18 °C

► HANDLING AND CONDITIONING

- Store rolls at -18 °C, sealed in original packages.
- Shop life at 23°C refers to rolls sealed in original packages.
- Before using the prepreg, remove the roll from the freezer and let it warm up to room temperature for 6 hours sealed in its original package.

GUARANTEE

The information of our technical data sheet is based on our present knowledge and the result of tests conducted under precise conditions. It is the responsibility of the user to determine the suitability of the products, under their own conditions before commencing with the proposed application. We refuse any guarantee about the compatibility of a product with any particular application. We disclaim all responsibility for damage from any incident, which results from the use of these products. The guarantee conditions are regulated by our general sale conditions.