




The external spring provides support to the swaged area and prevents kinking. Simply pull over the ferrule after swaging. The product is used in different processes of manufacturing and repair of parts from polymer composite materials.



TECHNICAL DATA	VALUE
Color	Silver
Maximum use temperature*	270°C

SIZE	
REFERENCE FOR ORDER	HOSE EXTERNAL DIAMETER
SK2VV232-14	3/8
SK2VV232-14A	1/2

**STORAGE**

It is recommended to store at temperature from -20°C until +30°C in the original packing.

**NOTES**

Recommended maintenance interval 1000 hours based on operating temperatures up to 180°C when used with our connections.

\* Maximum use pressure and temperature should be determined under your actual process conditions.

Technical values are provided to the best of our knowledge and are based on data considered reliable. Users are responsible for verifying suitability and assume all associated risks.